

# Stahura Conveyor Products

Conveyor Equipment Summary Sheet

Customer: XXXX



Belt Inspection Date: 12/15/22

Belt		Cleaner				
Name	Width	Position	Model	Condition	Date Serviced	Days in Service

Limestone

L1	42"	Primary	QC1HD	BLADE 50% WORN	6/18/21	545
		Secondary	SQC2S SAF	OK	6/18/21	545
		V Plow	RUBBER BLADE	OK	8/7/20	860
L2	30"	Primary	QC1HD	BLADE 50% WORN	3/4/22	286
		Secondary	SQC2S SAF	OK	9/30/22	76
		Secondary	SQC2S MR	OK	1/12/21	702
L3	30"	Primary	QC1HD	OK	12/6/22	9
		Secondary	SQC2S MINI MR	OK	9/3/21	468
		Secondary	SQC2S SAF	OK	4/14/22	245
L4	30"	Primary	QC1HD	OK	9/7/21	464
		Secondary	SQC2S MR	OK	9/7/21	464
		Secondary	SQC2S SAF	OK	9/30/22	76

Gypsum

G1 Feeder	42"	Primary	QC1HD	OK	2/18/22	300
G2 Feeder	42"	Primary	QC1HD	OK	2/18/22	300
G2	30"	Primary	QC1HD	OK	12/15/22	0
		Secondary (1st)	SQC2S SAF	OK	9/30/22	76
		Secondary (2nd)	SQC2S SAF	OK	12/15/22	0
		V Plow	RUBBER BLADE	OK	10/8/21	433

# Stahura Conveyor Products

Conveyor Equipment Summary Sheet

Customer: XXXX



Belt Inspection Date: 12/15/22

Belt		Cleaner				
Name	Width	Position	Model	Condition	Date Serviced	Days in Service
Washbox G2	30"	Secondary	SQC2S SAF	OK	11/12/21	398
		Secondary	SQC2S SAF	OK	11/12/21	398
G1A	30"	Primary	QC1HD	OK	6/22/22	176
		Secondary	SQC2S SAF #1	OK	8/8/22	129
		Secondary	SQC2S SAF #2	OK	8/8/22	129
Washbox G1A	30"	Secondary	SQC2S SAF	OK	6/22/22	176
		Secondary	SQC2S SAF	OK	6/22/22	176
G1B	30"	Primary	QC1HD	<b>BLADE 50% WORN</b>	10/5/22	71
		Secondary	DH2	OK	11/4/22	41
G3	30"	Primary	QC1HD	OK	11/4/22	41
		Secondary	SQC2S SAF	OK	1/12/21	702
		Secondary	SQC2S MR	OK	1/12/21	702
		Secondary	SQC2S MR	OK	11/3/19	1138
		V Plow	Tail	OK	5/26/22	203
G4	48"	Primary	QC1HD	OK	9/30/22	76
		Secondary	DH2	<b>BLADES/BONES NEED REPLACED</b>	2/18/22	300

**Coal**

13A	54"	Secondary (60" coverage)	SQC2S MR	OK	8/16/22	121
-----	-----	-----------------------------	----------	----	---------	-----

Walkdown Performed By: XXX